State Farm

BALES, ROBERT 36-29L1-57B

Source - Eagle View Source - Eagle View



R1

4,704.41 Surface Area 456.58 Total Perimeter Length 255.61 Total Hip Length 47.04 Number of Squares 85.28 Total Ridge Length

DESCRIPTION	QUANTITY	UNIT PRICE	TAX	RCV
R&R Tarp - all-purpose poly - per sq ft (labor and material)	10.00 SF	0.94	0.25	9.65
Remove Laminated - comp. shingle rfg (per SHINGLE)	5.00 EA	5.47	0.00	27.35
Laminated - comp. shingle rfg (per SHINGLE)	5.00 EA	13.16	0.97	66.77
Repairable wind damage found to left slope only				
R&R Roof vent - turtle type - Metal	4.00 EA	58.10	5.51	237.91
R&R Rain cap - 4" to 5"	3.00 EA	34.19	3.97	106.54
R&R Gutter / downspout - aluminum - up to 5"	10.00 LF	7.34	3.40	76.80

Left front downspout with small impact. No other guttering with damage consistent with hail.

No evidence of any circular bruises, fractures or punctures found to the roof surface. Markings circled by the roofer are not consistent with hail impacts, but rather normal wear, tear, mechanical and blistering damage.

Totals: R1		14.10	525.02
Area Totals: Source - Eagle View			
1,741.01 Exterior Wall Area			
4,704.41 Surface Area	47.04 Number of Squares	456.58 Total Perimeter Length	
85.28 Total Ridge Length	255.61 Total Hip Length		
Total: Source - Eagle View Area Totals: Source - Eagle View		14.10	525.02
1,741.01 Exterior Wall Area			
4,704.41 Surface Area	47.04 Number of Squares	456.58 Total Perimeter Length	
85.28 Total Ridge Length	255.61 Total Hip Length		
Total: Source - Eagle View		14.10	525.02

Date: 1/19/2022 1:04 PM Page: 4